

Draw Down

To determine the spreading rate at a specified level of dry film.
The basic procedure is to apply a uniform film on a suitable test substrate. To observe visually or photometrically its spreading rate.

Cat No. : 201 - A - Glossy

301 - A - Matt

Size App : 6" x 4"

Cat No. : 201 - E - Glossy

301 - E - Matt

Size App : 10" x 6"

Cat No. : 201 - G - Glossy

301 - G - Matt

Size App : 10" x 8"

